INFORMATION REPORT	
PARED AND DISSEMINATED BY	This material contains information affecting the National Defense of the United States within the meaning of the Espionage Laws. Title 18, U.S.C.
	Secs. 793 and 794, the transmission or revelation
CENTRAL INTELLIGENCE AGENCY	
Polarid	
Fort Information: Gdynia	17 APT 56 25X1
AVY review completed.	NO. OF PAGES NO. OF ENCLS.
AVI TOVIOW COMPLETED.	SUPPLEMENT TO REPORT #
THIS IS UNEVALUATED INFORMATI	25
THE OFFICE OF NAVAL INTELLIGENCE FURNISHED THE FO	
For hac dissimination in accordance with paragraph no 66-56).7	
#6 00-5015	# # #
and referred to in this report by the following al	phabetical designators:
A. Anchorage, Pilot Aboard B. Breakwater Entrance C. Buoy Missing D. Buoy Missing E. New White Flashing Light Buoy F. Berth G. Breakwater Entrance Closed H. Herchant Vessel Hull Under Construction I. Merchant Vessel Fitting Out (seven the J. Bunkering Station; Polish Merchant Tan Passenger Vessel K. Signal Tower L. Polish ED M. Moore-McCormack Line Merchant Vessel N. Moore-McCormack Line Merchant Vessel;	n (seven thousand tons) usand gross tons) ker; Polish Cargo-
A. Anchorage, Pilot Aboard B. Breakwater Entrance C. Buoy Missing D. Buoy Missing E. New White Flashing Light Buoy F. Berth G. Breakwater Entrance Closed H. Herchant Vessel Hull Under Construction I. Merchant Vessel Fitting Out (seven the J. Bunkering Station; Polish Merchant Tankersenger Vessel K. Signal Tower L. Polish ED M. Moore-McCormack Line Merchant Vessel	n (seven thousand tons) usand gross tons) ker; Polish Cargo-
A. Anchorage, Pilot Aboard B. Breakwater Entrance C. Buoy Missing D. Buoy Missing E. Mew White Flashing Light Buoy F. Berth G. Breakwater Entrance Closed H. Merchant Vessel Hull Under Construction I. Merchant Vessel Fitting Out (seven tho J. Bunkering Station; Polish Merchant Tan Passenger Vessel K. Signal Tower L. Polish ED M. Moore-McCormack Line Merchant Vessel B. Moore-McCormack Line Merchant Vessel; O. Inter-Club P. Polish Haval Training Vessel Approaches and Pilot Data entrance to subject port minefield pilot was engaged anchorage off subject port. A happer pilot boarde from a motor launch. He was an older man who could and conducted vessel both in and out of subject port	Vessel arrived off ed at designator A. A Baltic he conducted vessel as far as d vessel at anchorage 121300A d speak English only poorly rt on this call. His service re he boarded vessel at her
A. Anchorage, Pilot Aboard B. Breakwater Entrance C. Buoy Missing B. Buoy Missing B. Mew White Flashing Light Buoy F. Berth G. Breakwater Entrance Closed M. Merchant Vessel Hull Under Construction I. Merchant Vessel Fitting Out (seven thon J. Bunkering Station; Polish Merchant Tankering Station; Polish Merchant Tankersenger Vessel K. Signal Tower L. Polish ED M. Moore-McCormack Line Merchant Vessel N. Moore-McCormack Line Merchant Vessel; O. Inter-Club P. Polish Haval Training Vessel Approaches and Pilot Bata entrance to subject port minefield pilot was engaged anchorage off subject port. A happer pilot boarder from a motor launch. He was an older man who could and conducted vessel both in and out of subject por was satisfactory Qu departure	Vessel arrived off ed at designator A. A Baltic he conducted vessel as far as d vessel at anchorage 121300A d speak English only poorly rt on this call. His service re he boarded vessel at her

LIMITED: Dissembletian limited to full-time employees of CIA. AEC and FBI; and, within State and Defense, to the intelligence components, other offices producing NIS elements, and higher echeless with their immediate supporting statis. Not to be disseminated to consultants, external projects or reserve personnel on short term active duty texcepting individuals who are normally full-time employees of CIA. AEC, FBI, State or Defense) unless the written permission of the organizating effice has been obtained through the Assistant Director for Collection and Dissemination

C-O-N-F-I-D-K-N-T-I-A-L

. 2 . 25X1 Buring period of call weather was cold and windy. Average daily temperature ranged between 25°F and 38°F. Prevailing winds were from the Southwest at force 5. 25X1 vessel anchored on only one occasion during call, upon 4. Anchorage anchorage at this position is in 25X1 arrival at designator A. a good mud bottom. 25X1 5. Earbor vessel entered harbor through breakwater entrance labeled designator B. Buoys located at designators C and B were missing from positions shown on MO Chart No 4928. A new white light buoy is positioned at designator I mirking the southeast corner of the anchorage area. ressel moored at berth labeled designator F where control 6. Controls party boarded 121325A. Boarding party was composed of three men; doctor, customs officer, and immigration officer. The customs officer scaled all cameras, guns, and amunition, but did not seal vessel's radio, radar, master's sextant, provisions, binoculars, or personal effects. Vessel's erew members were not mustered and vessel was not searched. Boarding party departed vessel 121725A. On departure, vessel was not boarded. Shore passes were collected by a dock official, and no search of vessel took place. During period of call four armed guards were posted alongside vessel at her bow, stern, and two amidships on dock. Three of these guards carried rifles, and one at the gangway was armed with a "Submarhine gun. The guard armed with the Submarhine gun, who displayed one stripe on his uniform sleeve, appeared to be the non-commissioned officer in charge of the surveillance detail. No patrol craft was assigned surveillance duty in connection with source's vessel at any time during period of her call. All ever members were permitted to go ashore and all took advantage of the opportunity. 25X1 7. Harbor Craft ressel was assisted in berthing on arrival and in leave wharf on departure by two small tugs. Both of these were steam tugs of about ressel was assisted in berthing on arrival and in leaving 25X1 the tugs are "not too good," and 500 horsepower. 25X1 from the poor experience the vessel had in using them no dredges, salvage equipment, or ice breakers present in port 25X1 vessel moored 121320A with starboard side to Indian Quay at 25X1 berth labeled designator F. This berth is the only one alongside the grain elevator which is described in paragraph 17 below. depth alongside at this berth is 32°. Indian Quay is of stone construction and is 25X1 served by four railroad spur tracks liceated on apron between wharf facing and elevator structures. Water was supplied vessel at this berth by hoses. commenced discharging grain cargo 132330A into railroad cars on apron and completed discharge 180300A. 25X1 Area Between Northern Breakwater and Military Basin No 1 25X1 breakwater entrance shown on BO Chart No 4928 at designator G is closed. Sketch of the area between the Northern Breakwater and Military Basin To 1 follows:

C-O-N-F-I-D-K-H-T-I-A-L


HOFGRE

HO DISSIN AMERIAD

LIMITED



- 3 -



11. Mavail Installations in Oksywie Area, Including Military Basins 1 and 2

reported in paragraph 19 below.

relow one in lorustratur 13 peros.

25X1

25X1

12.

13.

14. Shippards

at the Paris Commune ship construction yard. A merchant vessel hull was under construction in either a marine way or 25X1 drydock at designator H.

the size of the hull as about seven thousand gross tons. A newly built merchant vessel was being fitted out alongside the northwest side of Basin No 5 at designator I. The latter vessel was estimated at about seven thousand gross tons also. Another new merchant vessel of estimated four thousand gross tons was observed undergoing trials in the area outside the harbor

25X1

C-O-M-F-I-D-E-M-T-I-A-L

Holden

NO DISSIM ARROAD

LIMITED

C-O-W-F-I-D-R-W-T-I-A-L


- 4 -25X1 15. Petroleum bunkering station at designator J. A Polish merchant tanker was moored alongand was engaged in 25X1 side at this berth discharging an unknown petroleum product. Four POL storage tanks are located on the Indian Quay at this berth. 25X1 16. 17. Greenry at Indian Quay. The granary councoded one large and two small through grain elevator concrete elevators. Grain cargo was underload vessel through two large permanent suction pipes and two portable Polish Army suction pipes 25X1 mounted on railroad cars. Only one vessel may be loading or unloading cargo at this granary at a time. Cargo from vessel was discharged directly into railroad cars standing on spur tracks on wharf apron. 25X1 18. Hel Peninsula signal tower at designator K. 25X1 a 350°, one-stack Polish DD moored at berth 19. Maval Vessels labeled designator L The destroyer appeared to be the GROM class DD, BLYSKAWICA, a Polish maval training vessel moored at designator P, 25X1 20. Merchant Vessels 25X1 a Polish merchant tanker moored ahead of his vessel at designator J at the small bunker station on the Indian Quay discharging an unknown petroleum cargo into PCL storage tanks on the Quay. the departure of the Polish tanker at designator J, a Polish cargo-passenger vessel moored at the same berth on 17 Nov 55 and discharged a general cargo. 25X1 21. Miscellaneous Crew members spent most of their time ashore at the "Inter-Club" located at designator 0. Refreshments at reasonable prices were available at this cabaret provided for visiting foreign merchant ships, and entertainment in the form of movies was presented. Hostesses were available at this club for dancing and talking, but seemen were warned that prostitution was not permitted and that advances were not to be made to the girls. The hostesses serve one night a week at the club and are employed on a full-time basis in factory work during the days. A wide variety of chandlery goods was available at subject port, including good quality Polish beef and mutton, Czech beer, and imported cheese Butter is among 25X1 the products still rationed to Polish citizens, and on several occasions Polish individuals boarding vessel on business remarked about the shortages existing in consumer goods in that area. Commont It is noted that security regulations for subject port with respect to the boarding and searching of foreign merchant vessels have been relaxed. Ship construction in the Paris Commune 25X1 yard appears to be very active. all cameras were surrendered for sealing by the boarding party. 7 C-O-M-F-I-D-E-M-T-I-A-L

Approved For Release 2008/07/25 : CIA-RDP80-00926A008400680001-9


NO DISSEM ABROAD

LIMITED

HOPORT



Approved For Release 2008/07/25: CIA-RDP80-00926A008400680001-9



Plan Viete Ser 1955

COMPIDENTIAL.

25X1

